

Product Safety Recall



Product Name

ABS AVALANCHE AIRBAG GREY STEEL CANNISTER

[Pre 2 December 2014]

Defect: The producer and filler of ABS steel canisters has detected problems in the filling process and it is possible that steel cartridges filled on or before 2 December 2014 may have been contaminated during filling. The contamination could block the airbag system during activation and cause the airbags to not inflate as expected. Does not apply to carbon canisters or yellow steel canisters.

Hazard: Airbags not inflating during an emergency, airbag system becoming contaminated and causing problems with inflation in the future.

What to do: Please contact ASAP to receive a replacement and do not use your current ABS airbag.

Contact details: Brandex Adventure Sports

phone: 03 381 2190

email: anna@brandex.co.nz

online: www.brandex.co.nz

New Zealand Importer/Distributor

Company Name: Brandex

Address: 204 Cumnor Tce, Woolston, Christchurch

Country: NZ

Phone : 03 381 2190

See www.consumeraffairs.govt.nz for
other New Zealand consumer product recalls